

WARNING

THIS FIRE INDICATOR PANEL IS CONNECTED TO A GASEOUS FIRE SUPPRESSION SYSTEM THAT CONTAINS A SCHEDULED EXTINGUISHING AGENT THAT IF RELEASED INTO THE ATMOSPHERE, MAY DEplete THE OZONE LAYER OR ADD TO GLOBAL WARMING.

Technicians working on this gaseous fire suppression system are required to hold a current Extinguishing Agent Handling Licence (EAHL) as issued by the Fire Protection Industry (ODS & SGG) Board (the Board).

Technicians are reminded to use the correct procedures when working on this panel to prevent an accidental discharge of the system, such as:

- Isolating the actuation circuit and removing the actuators from the gaseous fire suppression system containers before undertaking any testing or maintenance activities.
- Re-installing the actuators only after the fire detection and control system has been placed back into its normal state and all alarm conditions cleared.

The Board recommends any accidental discharge of extinguishing agent from this system to be reported to the Board:

Call: 03 8892 3131

Email: ozone@fpib.com.au

